



## Bridge Work.

This Bridge in Scotland looks solid, but the top section is in fact lightweight GRP.

Once the local vandals found out it was hollow, they started vandalising it. The voids were filled with high density foam which made the structure strong enough to resist their efforts to break it

