



Listed Buildings.

This picture shows a listed Cruick Barn being treated internally .
Timbers are masked before treatment.

Class 1 fire rated spray foam was applied between rafters and in this instance, painted a light brown colour to the customers specification prior to removing the masking.

The treatment provides insulation, permanently bonds the slates in place and eliminates air leakage.

